




Foundation drawing



Layout
Shown with table extended



NOTES:

- 1) 220V,40A,3 PHASE FOR 1KW MACHINES.
- 2) 220V,50A,3PHASE FOR 2KW MACHINES.
- 3) 3KW and UP REQUIRES 480V, 60A, 3 PHASE FOR THE OPTICAL SUPPLY TRANSFORMER. 220V,40A,3 PHASE FOR MACHINE MOTION.

FC ENCLOSURE, NO SHUTTLE

NTS

DRN SB

3/24/2025,REV3

LAGUNA